


1969 CHRYSLER CORP. ANTI-ICING DEVICE

All 170-225" 6-Cylinder, and some 318" V8 Engines (1969 Only) — Anti-icing device is installed to prevent ice formation on throttle valves during warm-up. Ice formation blocks passage of air and engine stalls. To prevent occurrence of ice formation, exhaust manifold has heat tube installed

leading to hoses connected to air cleaner and carburetor base supplying preheated air to throttle valves. No service procedures are required to maintain device. Periodic inspection is required to keep device operating efficiently.



9CH001

ANTI-ICING DEVICE (1969 ONLY)