


1981 General Motors

"P" Models

5-27

WIRING DIAGRAMS



CONN. A


| | | | |
|-----|----|----|-----|
| 2J | 31 | | |
| | 35 | 2E | 25 |
| 241 | 39 | 30 | 33 |
| 6 | 3 | | 931 |



CONN. B

| | | | |
|----|----|----|----|
| 12 | 15 | 14 | 11 |
| | 9 | | 20 |

CONN. C

| | | | | |
|----|--|--|--|---|
| 24 | | | | 9 |
|----|--|--|--|---|





- 8 INST. LTS.
- 11 HIGH BEAM
- 30 FUEL GAUGE
- 31 OIL PRESS
- 33 BRAKE SW.
- 35 TEMP. GA.
- 39 IGN.
- 100 GROUND

