

1975 TUNE-UP SPECIFICATIONS

ENGINE	IGNITION TIMING		DISTRIBUTOR		SPARK PLUGS		CARBURETOR	No.
	Man. Trans.	Auto. Trans.	Cam Angle	Point Gap	Type	Gap	Make & Type	
FORD MOTOR CO.								
2300cc 4 Cyl.	③	③	②	②	AL AGRF52	.034"	Ford 5200	38
200" 6 Cyl.	③	③	②	②	AL BRF-82	.042-.046"	Car. YFA	39
250" 6 Cyl.	③	③	②	②	AL BRF82	.042-.046"	Car. YFA	40
2800cc V6								
Federal	③	③	②	②	AL AGR42	.032-.036"	Ford 2150	41
Calif.	③	③	②	②	AL AGR42	.032-.036"	Ford 2150	42
302" V8	③	③	②	②	AL ARF42	.042-.046"	Ford 2150	43
351" V8	③	③	②	②	AL ARF42	.042-.046"	Ford 2150	44
400" V8	③	③	②	②	AL ARF42	.042-.046"	Ford 2150	45
460" V8	③	③	②	②	AL ARF52	.042-.046"	Ford 4350	46
460" V8 Police	③	③	②	②	AL ARF52	.042-.046"	Ford 4350	47
OLDSMOBILE								
231" V6	12°B	12°B	①	①	AC R44SX	.060"	Roch. 2GC	48
250" 6 Cyl.								
Federal	10°B	10°B	①	①	AC R46TX	.060"	Roch. 1MV	49
Calif.	10°B	①	①	AC R46TX	.060"	Roch. 1MV	50
260" V8								
Federal	16°B	18°B	①	①	AC R46SX	.080"	Roch. 2MC	51
Calif.	16°B④	①	①	AC R46SX	.080"	Roch. 2MC	52
350" V8 2-Bbl.	12°B	①	①	AC R45TSX	.060"	Roch. 2GC	53
350" V8 4-Bbl.								
Omega	12°B	12°B	①	①	AC R45TSX	.060"	Roch. M4MC	54
Cutlass	20°B	①	①	AC R46SX	.080"	Roch. M4MC	55
400" V8 2-Bbl.	16°B	①	①	AC R45TSX	.060"	Roch. 2GC	56
400" V8 4-Bbl.	16°B	16°B	①	①	AC R45TSX	.060"	Roch. M4MC	57
455" V8								
Cutlass, 88 & 98	16°B	①	①	AC R46SX	.080"	Roch. M4MC	58
Toronado	12°B	①	①	AC R46SX	.080"	Roch. M4MC	59
PONTIAC								
140" 4 Cyl. 1-Bbl.	8°B	10°B	①	①	AC R43TSX	.060"	Roch. 1MV	60
140" 4 Cyl. 2-Bbl.	10°B	12°B	①	①	AC R43TSX	.060"	Hol. 5210C	61
250" 6 Cyl.	10°B	10°B	①	①	AC R46TX	.060"	Roch. 1MV	62
260" V8								
Federal	16°B	18°B	①	①	AC R46SX	.080"	Roch. 2MC	63
Calif.	16°B	①	①	AC R46SX	.080"	Roch. 2MC	64
350" V8 2-Bbl.	16°B④	①	①	AC R46TSX③	.060"	Roch. 2GC	65
350" V8 4-Bbl.								
Federal	12°B	16°B④	①	①	AC R46TSX③	.060"	Roch. M4MC	66
Calif.	12°B	①	①	AC R46TSX③	.060"	Roch. M4MC	67
400" V8 2-Bbl.	16°B	①	①	AC R46TSX	.060"	Roch. 2GC	68
400" V8 4-Bbl.								
Federal	12°B	16°B	①	①	AC R45TSX	.060"	Roch. M4MC⑦	69
Calif.	12°B	①	①	AC R45TSX	.060"	Roch. M4MC⑦	70
455" V8 4-Bbl.								
Federal	16°B	①	①	AC R45TSX	.060"	Roch. M4MCA	71
Calif.	10°B	①	①	AC R45TSX	.060"	Roch. M4MCA	72

IGNITION TIMING: B - BTDC, A - ATDC.

SPARK PLUGS: AL - Autolite, CH - Champion.

CARBURETORS: Car. - Carter, Hol. - Holley, Roch. - Rochester.

1975 TUNE-UP SPECIFICATIONS

T-5

No.	HOT IDLE * *		FAST IDLE			IDLE CO %		Remarks	
	Man. Trans.	Auto. Trans.	Man. Trans.	Auto. Trans.	RPM	Man	Auto		
			RPM	Cam Step					
38	③	③	1800	③	1800	③	③	① - On 351"W, 1400. ② - Electronic ignition. ③ - See Engine Tune-Up Decal.	
39	③	③	1700	③	1700	③	③		
40	③	③	1700	③	1700	③	③		
41	③	③	1600	③	1600	③	③		
42	③	③	1600	③	1600	③	③		
43	③	③	2000	③	2100	③	③		
44	③	③	1350①	③	1350①	③	③		
45	③	③	1500	③	1500	③	③		
46	③	③	1350	③	1350	③	③		
47	③	③	1350	③	1350	③	③		
48	800/600	650/500②	1800	Low	1800	③	③		① - Electronic ignition. ② - Auto. trans. in "D". ③ - See Engine Tune-Up Decal. ④ - On Omega, 14°B. ⑤ - In Calif., 600. ⑥ - In Calif., 1000. ⑦ - Fed. 88 Wagon & 98 Sedan, 625. ⑧ - In Calif., 800.
49	850/425	550/425②	1800	High	1700	③	③		
50	600/425②	High	1700	③		
51	750	650/550②	900	Low	900	③	③		
52	650/600②	Low	900	③		
53	650/600	600	Preset	③		
54	600	650/600②	1800	Low	1800	③	③		
55	650/550②③	Low	900④	③		
56	650	Low	1800	③		
57	650②⑦	1800	Low	1800	③	③		
58	650/550②③	Low	900⑧	③		
59	650/550②③	Low	900⑧	③		
60	700/1000	550/750	2000	High	2200	③	③	① - Electronic ignition. ② - In Calif., 600/425. ③ - See Engine Tune-Up Decal. ④ - On Ventura, 12°B. ⑤ - On Ventura, R45TSX. ⑥ - Safari Wagons, 625. ⑦ - Some use an M4MCA. ⑧ - Higher RPM, Calif. Only.	
61	700/1000③	600/750	1600	2nd	1600	③	③		
62	850/425	550/425②	1800	High	1800	③	③		
63	③	③	③	High	③	③	③		
64	③	③	③	High	③	③	③		
65	600/425	High	1700	③		
66	775	650	1800	High	1800	③	③		
67	625	High	1800	③		
68	650	High	1800	③		
69	775	650⑥	1800	High	1800	③	③		
70	600	High	1800	③		
71	650	High	1800	③		
72	675	High	1800	③		

* - When idle solenoid is used, higher RPM is with solenoid connected; lower RPM, solenoid disconnected.

* - With A/C, higher RPM is with "A/C On" and clutch leads disconnected. Low RPM is with "A/C Off".